

Car Initial: **XYZ** Car Number: **1016** Kind: **G** Responsibility of: **XYZ, Inc.**

D/C Initial

D/C Date:

Estimate Repair Date: **09/10/2003**

Estimated at **123456** -

1	LO	Qty	C	Applied		Description	WM	Removed		RESP	Labor	Material	Total
				C	Job			QF	Job				
	A	1.0	1	1630	00	AIR BRAKE HOSE 33" OR OVER	21	1630	00	1	5.33	30.40	35.73
2	4	1.0	3	3276	00	AXLE-RWS-ROLLER BRG, 6 1/2 X 12 IN JRNL	11	3276	00	1	0.00	0.00	0.00
3	4	1.0	3	3337	00	TURNED WHEEL SET COMP 36, 6 1/2X12 AXLE	09	3337	00	1	35.73	584.79	620.52
4	C	4.0	1	3912	00	TRUCK SPRING, OUTER COIL, D5	25	3912	00	1	20.12	46.08	66.20
5	C	4.0	1	3932	00	TRUCK SPRING, INNER COIL, D6	25	3932	00	1	20.12	19.44	39.56
6	C	2.0	1	4458	00	LABOR, JACK CAR	09	4458	00	1	71.30	0.28	71.58
7	R4	1.0	4	3071	02	WHEEL 36" 1W HT-CP (0290SWC20003200	64	3071	02	1	0.00	0.00	0.00
8	L4	1.0	4	3071	02	WHEEL 36" 1W HT-CP (0290SWC20003200	11	3071	02	1	0.00	0.00	0.00
9	R4	1.0	3	2816	03	ROLLER BEARING, GROUP B,6-1/2X12 IN.	11	2816	03	1	0.00	0.00	0.00
10	L4	1.0	3	2816	03	ROLLER BEARING, GROUP B,6-1/2X12 IN.	11	2816	03	1	0.00	0.00	0.00
11	C	2.0	6	4340	KA	STD. TEMP. AEI TAG-(ACI LABEL)	25	4340	KA	1	39.81	0.00	39.81
12	C	4.0	1	4414	RU	BOLT,HT,3/4" DIA.OR -(TOP CHORD ANGLE)	09	4414	RU	1	20.30	4.24	24.54
13	C	640.0	0	4808	RU	BUTT JOINT WELD, OVE-(TOP CHORD ANGLE)	09	4808	RU	1	1485.53	0.00	1,485.53
14	C	6.0	0	4450	ZF	LABOR, REMOVE INTERIOR BRACING	25	4450	ZF	1	258.00	0.00	258.00

**Total Amount**      \$ 1956.24      \$ 685.23      2,641.47

**Total AAR Labor = 3480.75 minus discount of 1524.51 equals 1956.24**

Car Initial: **XYZ** Car Number: **1056** Kind: **G** Responsibility of: **XYZ, Inc.**

D/C Initial D/C Date:

Estimate Repair Date: **09/30/2003** Estimated at **123456** -

1	LO	Qty	C	Applied		Description	WM	Removed		RESP	Labor	Material	Total
				C	Job			QF	Job				
	C	1.0	7	1143	00	SINGLE CAR ABT, W/O BRAKE CYL TAP,1 SET	21	1143	00	1	0.00	0.00	0.00
2	C	2.0	1	1630	00	AIR BRAKE HOSE 33" OR OVER	21	1630	00	1	10.67	60.80	71.47
3	R	4.0	1	1838	00	BRAKE SHOE-COMP. HI-FRCT 1-1/2 IN.	01	1838	00	1	21.15	35.36	56.51
4	L3	1.0	1	1838	00	BRAKE SHOE-COMP. HI-FRCT 1-1/2 IN.	01	1838	00	1	5.29	8.84	14.13
5	L4	1.0	1	1838	00	BRAKE SHOE-COMP. HI-FRCT 1-1/2 IN.	01	1838	00	1	5.29	8.84	14.13
6	C	4.0	1	3912	00	TRUCK SPRING, OUTER COIL, D5	25	3912	00	1	20.12	46.08	66.20
7	C	4.0	1	3932	00	TRUCK SPRING, INNER COIL, D6	25	3932	00	1	20.12	19.44	39.56
8	C	2.0	1	4458	00	LABOR, JACK CAR	09	4458	00	1	71.30	0.28	71.58
9	C	2.0	6	4340	KA	STD. TEMP. AEI TAG-(ACI LABEL)	25	4340	KA	1	39.81	0.00	39.81
10	C	4.0	1	4414	RU	BOLT,HT,3/4" DIA.OR -(TOP CHORD ANGLE)	09	4414	RU	1	20.30	4.24	24.54
11	C	640.0	0	4808	RU	BUTT JOINT WELD, OVE-(TOP CHORD ANGLE)	09	4808	RU	1	1485.53	0.00	1,485.53
12	C	6.0	0	4450	ZF	LABOR, REMOVE INTERIOR BRACING	25	4450	ZF	1	258.00	0.00	258.00

**Total Amount**      \$ 1957.58      \$ 183.88      **2,141.46**

**Total AAR Labor = 3483.12 minus discount of 1525.54 equals 1957.58**