

# Joint Inspection Certificate

Company Name **The DEMO Company, LLC**  
 Address **1886 Lynwood Drive**  
 City/State/ZIP **Concord, CA 94519**  
 Telephone **(409) 745-4696**  
 Fax **No Fax Available**

Defect Card Attached  YES  
 NO

ISSUED BY: **ABCD**  
 DATE ISSUED **07/13/2004**  
 LOCATION: **Allentown, Pennsylvania**

Car  
 Rack \_\_\_\_\_  
Owner

PREPARATION COMPANY: **The Demo Company, LLC**  
 LOCATION: **Concord, California**  
 DATE OF PREPERATION: **August 11, 2008**

Car Arrived on own Wheels  Yes  No Loaded on Car Initial \_\_\_\_\_ Car No. \_\_\_\_\_

The undersigned have personally inspected Car XYZ No. 123456 and found the following conditions:

LOCATION	DEFECTIVE ITEMS	NATURE OF DEFECTS
1	JIC COVERS ALL DAMAGES, DEFECT CARD TO BE RETURNED FOR CANCELLATION AT TIME OF INVOICING.	
2 AR	PATCH HOLE IN SIDE SHEET	Broken or visually cracked
3 1	APPLY NEW HOPPER GATE	Broken or visually cracked
4 2	APPLY NEW HOPPER GATE	Broken or visually cracked
5 3	APPLY NEW HOPPER GATE	Broken or visually cracked
6 A	H/STRAIGHTEN HOPPER CHUTES	Bent
7 A	PATCH HOLES IN HOPPER CHUTE	Broken or visually cracked
8 B	H/STRAIGHTEN HOPPER CHUTES	Bent
9 B	PATCH HOLES IN HOPPER CHUTE	Broken or visually cracked
10 A	H/STRAIGHTEN SHAKER PADS	Bent
11 B	H/STRAIGHTEN SHAKER PADS	Bent
12 L	H/STRAIGHTEN CHUTE SIDE AND END PLATES	Bent
13 B	REPLACE SILL STEPS	Broken or visually cracked
14 AR	REPLACE SILL STEP	Broken or visually cracked
15 AL	H/STRAIGHTEN SILL STEP	Bent

# Joint Inspection Certificate

Company Name **The DEMO Company, LLC**  
 Address **1886 Lynwood Drive**  
 City/State/ZIP **Concord, CA 94519**  
 Telephone **(409) 745-4696**  
 Fax **No Fax Available**

Defect Card Attached  YES  
 NO

ISSUED BY: **ABCD**  
 DATE ISSUED **07/13/2004**  
 LOCATION: **Allentown, Pennsylvania**

Car  
 Rack \_\_\_\_\_  
Owner

PREPARATION COMPANY: **The Demo Company, LLC**  
 LOCATION: **Concord, California**  
 DATE OF PREPERATION: **August 11, 2008**

Car Arrived on own Wheels  Yes  No Loaded on Car Initial \_\_\_\_\_ Car No. \_\_\_\_\_

The undersigned have personally inspected Car XYZ No. 123456 and found the following conditions:

LOCATION	DEFECTIVE ITEMS	NATURE OF DEFECTS
16 A	H/STRAIGHTEN SIDE LADDERS	Bent
17 BL	REPLACE SIDE LADDER	Broken or visually cracked
18 AR	H/STRAIGHTEN END LADDER	Bent
19 AL	H/STRAIGHTEN CORNER POST	Bent
20 BL	REPLACE CORNER POST	Broken or visually cracked
21 BL	REPLACE SIDE POST	Broken or visually cracked
22 L	H/STRAIGHTEN SIDE SILL, ANGLES AND DRESS	Bent
23 R	H/STRAIGHTEN SIDE SILL, ANGLES AND DRESS	Bent
24 A	REPLACE END SILL ANGLE	BENT BEYOND REPAIRS
25 A	H/STRAIGHTEN END RUNNING BOARD	Bent
26 A	H/STR. RUNNING BOARD BRACKETS (3 TOTAL)	Bent
27 AL	REPLACE END ANGLE POST	BENT BEYOND REPAIRS
28 A	H/STRAIGHTEN END HANDRAIL	Bent
29 AL	H/STRAIGHTEN STRIKER SIDE IRON	Bent
30 AL	REPLACE ANGLE COCK BRACKET	BENT BEYOND REPAIRS
31 AL	H/STRAIGHTEN DRAFT SILL BRAKE LEVER	Bent
32 L	H/STRAIGHTEN END SILL STIFFENER ANGLES	Bent

# Joint Inspection Certificate

Company Name **The DEMO Company, LLC**  
 Address **1886 Lynwood Drive**  
 City/State/ZIP **Concord, CA 94519**  
 Telephone **(409) 745-4696**  
 Fax **No Fax Available**

Defect Card Attached  YES  
 NO

ISSUED BY: **ABCD**  
 DATE ISSUED **07/13/2004**  
 LOCATION: **Allentown, Pennsylvania**

Car  
 Rack \_\_\_\_\_  
Owner

PREPARATION COMPANY: **The Demo Company, LLC**  
 LOCATION: **Concord, California**  
 DATE OF PREPERATION: **August 11, 2008**

Car Arrived on own Wheels  Yes  No Loaded on Car Initial \_\_\_\_\_ Car No. \_\_\_\_\_

The undersigned have personally inspected Car XYZ No. 123456 and found the following conditions:

LOCATION	DEFECTIVE ITEMS	NATURE OF DEFECTS
33 A	REPLACE COUPLER CARRIER AND WELD (32")	Broken or visually cracked
34 AL	REPLACE BOTTOM FLANGE ON BODY BEARING	BENT BEYOND REPAIRS
35 L	H/STRAIGHTEN BODY BOLSTER FLANGES	Bent
36 L1	APPLY TRANSDYNE ROOF LINER	Missing
37 L2	APPLY TRANSDYNE ROOF LINER	Missing
38 L3	APPLY TRANSDYNE ROOF LINER	Missing
39 L4	APPLY TRANSDYNE ROOF LINER	Missing
40 R1	APPLY TRANSDYNE ROOF LINER	Missing
41 R2	APPLY TRANSDYNE ROOF LINER	Missing
42 R3	APPLY TRANSDYNE ROOF LINER	Missing
43 R4	APPLY TRANSDYNE ROOF LINER	Missing
44 A	APPLY 2" HF COMP. BRAKE SHOES	Missing
45 A	APPLY BRAKE SHOE KEYS	Missing
46 B	APPLY 2" HF COMP. BRAKE SHOES	Missing
47 B	APPLY BRAKE SHOE KEYS	Missing
48 B	H/STRAIGHTEN UNCOUPLING LEVER BRACKET	Bent
49 B	REPLACE UNCOUPLING LEVER	Missing
50 A	REPLACE UNCOUPLING LEVER	Missing

# Joint Inspection Certificate

Company Name **The DEMO Company, LLC**  
 Address **1886 Lynwood Drive**  
 City/State/ZIP **Concord, CA 94519**  
 Telephone **(409) 745-4696**  
 Fax **No Fax Available**

Defect Card Attached  YES  
 NO

ISSUED BY: **ABCD**  
 DATE ISSUED **07/13/2004**  
 LOCATION: **Allentown, Pennsylvania**

Car  
 Rack  
 \_\_\_\_\_  
 Owner

PREPARATION COMPANY: **The Demo Company, LLC**  
 LOCATION: **Concord, California**  
 DATE OF PREPERATION: **August 11, 2008**

Car Arrived on own Wheels  Yes  No Loaded on Car Initial \_\_\_\_\_ Car No. \_\_\_\_\_

The undersigned have personally inspected Car XYZ No. 123456 and found the following conditions:

LOCATION	DEFECTIVE ITEMS	NATURE OF DEFECTS
51 2	APPLY #18 BRAKE BEAM	Missing
52 4	APPLY #18 BRAKE BEAM	Missing
53 A	H/STRAIGHTEN TOP END PLATE	Bent
54 AR	APPLY STUCKI HYDRAULIC SNUBBER UNIT	Missing
55 L	APPLY D6A SPRINGS	Missing
56 R	APPLY D6A SPRINGS	Missing
57 AL	H/STR. BODY BEARING STIFFENER PLATES	Bent
58 A	REPLACE TOP END RUNNING BOARD	BENT BEYOND REPAIRS
59 A	REPLACE CROSSOVER BOARD	BENT BEYOND REPAIRS
60 B	REPLACE TOP END RUNNING BOARD	BENT BEYOND REPAIRS
61 B	REPLACE CROSSOVER BOARD	BENT BEYOND REPAIRS
62 L	REPLACE TOP SIDE RUNNING BOARDS	Broken or visually cracked
63 R	REPLACE TOP SIDE RUNNING BOARDS	BENT BEYOND REPAIRS
64 R	REPLACE TOP SIDE RUNNING BOARD BRKTS	BENT BEYOND REPAIRS
65 AR	G/WELD CRACKED END RUNNING BOARD BRKT	Broken or visually cracked
66 A	REPLACE FIBREGLASS HATCH COVERS	Broken or visually cracked
67 A	REPLACE BATTEN BARS	Broken or visually cracked

# Joint Inspection Certificate

Company Name **The DEMO Company, LLC**  
 Address **1886 Lynwood Drive**  
 City/State/ZIP **Concord, CA 94519**  
 Telephone **(409) 745-4696**  
 Fax **No Fax Available**

Defect Card Attached  YES  
 NO

ISSUED BY: **ABCD**  
 DATE ISSUED **07/13/2004**  
 LOCATION: **Allentown, Pennsylvania**

Car  
 Rack \_\_\_\_\_  
Owner

PREPARATION COMPANY: **The Demo Company, LLC**  
 LOCATION: **Concord, California**  
 DATE OF PREPERATION: **August 11, 2008**

Car Arrived on own Wheels  Yes  No Loaded on Car Initial \_\_\_\_\_ Car No. \_\_\_\_\_

The undersigned have personally inspected Car XYZ No. 123456 and found the following conditions:

LOCATION	DEFECTIVE ITEMS	NATURE OF DEFECTS
68 B	REPLACE FIBREGLASS HATCH COVERS	Broken or visually cracked
69 B	REPLACE BATTEN BARS	Broken or visually cracked
70 AL	REPLACE BODY BEARING SHIMS	Adjust clearance
71 A	APPLY BRAKE LEVERS	Missing
72 A	APPLY 7/8" BRAKE RODS C/W FITTINGS	Missing
73 A	APPLY COTTER PINS FOR ABOVE	Missing
74 A	APPLY BRAKE PINS	Missing
75 B	APPLY BRAKE LEVERS	Missing
76 B	APPLY 7/8" BRAKE RODS C/W FITTINGS	Missing
77 B	APPLY COTTER PINS FOR ABOVE	Missing
78 B	APPLY BRAKE PINS	Missing

# Joint Inspection Certificate

Company Name **The DEMO Company, LLC**  
 Address **1886 Lynwood Drive**  
 City/State/ZIP **Concord, CA 94519**  
 Telephone **(409) 745-4696**  
 Fax **No Fax Available**

Defect Card Attached  YES  
 NO

ISSUED BY: **ABCD**  
 DATE ISSUED **07/13/2004**  
 LOCATION: **Allentown, Pennsylvania**

Car  
 Rack \_\_\_\_\_  
Owner

PREPARATION COMPANY: **The Demo Company, LLC**  
 LOCATION: **Concord, California**  
 DATE OF PREPERATION: **August 11, 2008**

Car Arrived on own Wheels  Yes  No    Loaded on Car Initial \_\_\_\_\_ Car No. \_\_\_\_\_

The undersigned have personally inspected Car XYZ No. 123456 and found the following conditions:

LOCATION	DEFECTIVE ITEMS	NATURE OF DEFECTS
----------	-----------------	-------------------

INSPECTOR: \_\_\_\_\_ INSPECTED FOR \_\_\_\_\_  
John Walker Joe E. Repair

INSPECTOR: \_\_\_\_\_ INSPECTED FOR \_\_\_\_\_  
James Beam Tom Freitas

**THESE SIGNATURES DO NOT CONSTITUTE ENDORSEMENT (SEE RULE 103)**

OWNER DEFECTS Per Rule 108:	EST. COST OF REPAIR	LABOR \$ _____	MATERIAL \$ _____	TOTAL \$ _____
RETURNING CAR ON OTHER EQUIPMENT	YES <input type="checkbox"/> NO <input type="checkbox"/>	HANDLING LINE WILL MAKE COMPLETE REPAIRS		YES <input type="checkbox"/> NO <input type="checkbox"/>
PARTIAL REPAIRS	YES <input type="checkbox"/> NO <input type="checkbox"/>	TEMPORARY REPAIRS		YES <input type="checkbox"/> NO <input type="checkbox"/>